

# Super Dry<sup>™</sup> sD-900

# Int/Ext 15 Min. Drying Polyurethane High-Gloss Enamel

## **Description:**

**Super Dry**<sup>™</sup> is an alkyd and polyurethane resin paint enamel of premium quality and high gloss finish that protects against corrosion, to be used where a fast drying application is needed. Excellent adhesion and color retention properties. It guarantees one-coat coverage over any color or surface, interior or exterior. For use on metal, concrete, wood and brick.

# **Meets Requirements for:**

MPI:	N/A
Green Performance1:	N/A
Green Performance 2:	N/A
VOC Compliant (<200g/L):	NO
SCAQMD:	N/A
AIM & OTC:	N/A

### **Product Advantages:**

- Excellent protection against corrosion
- Excellent color retention
- Non-vellowing
- · Chip and flake resistant
- 15 minutes drving
- Rust resistant
- Good exterior durability and tough
- Heavy metal and lead free
- · Impact and abrasion resistant

## **Available Colors:**

White SD900	Black SD904
Bone White SD918	Navy SD923
Red SD931	Blue SD932
Caterpillar SD933	Mahogany SD935
Land SD938	Titanium Yellow SD939
Hunter Green SD940	Old San Juan SD919

### Uses:

Super Dry™ is ideal for use over prepared substrates in industrial enviroments and surfaces where there is need of a fast drying. durable and strong paint against rust, stain and dirt. May be applied with brush, roller or sprayer on any industrial, commercial or residential area, like equipments, pipes, steel supports, railings, etc. For new or previously painted metal, wood, stucco, brick or concrete.

### **Technical Data:**

Alkyd Resin Product Type:

Finish: Gloss (> 80°)

\*Geometry 60°

 $59 \pm 2\%$  by weight  $43 \pm 2\%$  by volume Solids (%):

Weight/Gallon:  $10.0 \pm 0.05$  lbs.  $(4.8 \pm 0.02 \text{ kg.})$ 

Colors: Tinting Bases and

Ready Mix Colors

Drying Time:

To touch: 10 - 15 min.

To recoat: 2 - 4 hrs.

Coverage:

Up to 680 ft.2 per Theorethical:

gallon @ 1 mil

Recommended: 450-500 ft.2/gal.

(41-45 m<sup>2</sup>/gal.) @ 1.5 dry mils, 4 wet mils

1 gallon Sizes:

1 auart

Thinning: Is not recommended.

Flash Point: 78 °F TOC

Viscosity: 70 - 80 KU's

Percent Pigment

by Weight:  $23 \pm 2\%$ 

VOC: <500 g/L

Notice: The technical data contained herein are true and accurate to the best of our knowledge. Published technical data and instructions are subject to change without prior notice.

S.D.S.: Available upon request.

# **Surface Preparation:**

All surfaces must be dry, clean, sound and free of contaminants. Remove all dirt, grease, chalk. mildew, oil, rust, concrete curing agents, dust, and other soluble contaminants from steel surfaces by washing with solvent, vapor, cleaning compound or other method.

Remove all loose mill scale, loose rust, loose paint, and other loose detrimental foreign matter by hand chipping, scraping, sanding, and wire brushing or by power wire brushing, power sanding, power grinding, power tool chipping, and power tool descaling.

Prime if required as per recommended specifications of this product for surfaces like: concrete, plasters, gypsum wallboard, drywall, wood, plywood, steel, aluminum, galvanized steel, other composition materials or vinyl siding with the recommended Lanco® primer or primer/sealer, following application instructions. Glossy surfaces should be lightly sanded and primed previous to new paint application.

### **Recommended Paint Systems:**

# Iron and Steel:

Surface preparation: SSPC-SP2/SP3 Primer, apply 1 coat: Oil-Red Oxide Prime Paint, apply 2 coats: Super Drv™

#### Galvanized Metal and Aluminum:

Surface preparation: SSPC-SP1

Primer, apply 1 coat: Oil-White Galvanized Paint, apply 2 coats: Super Dry™

# Masonry and Concrete:

Surface preparation: SSPC-SP13 Primer, apply 1 coat: Stain Killer™ Primer Paint, apply 2 coats: Super Dry™

# Wood:

Surface preparation: Dry and Clean Stain Killer™ Primer Primer, apply 1 coat: Paint, apply 2 coats: Super Dry™

### **Surface Preparation Standards:**

# **SSPC-SP1 Solvent Cleaning**

Removal of all visible oil, grease, soil, drawing and cutting compounds, and other soluble contaminants from steel surfaces with solvent LANCO® Lacquer Thinner LT-102, vapor cleaning, alkali, emulsifying agent, or steam.

#### SSPC-SP2 Hand Tool Cleaning

Removes all loose mill scale, loose rust, loose paint, and other loose foreign matter by hand chipping, scraping, sanding, and wire brushing.

### **SSPC-SP3 Power Tool Cleaning**

Removes all loose mill scale, loose rust, loose paint, and other loose detrimental foreign matter by power wire brushing, power sanding, power grinding, power tool chipping, and power tool descaling.

# SSPC-SP7 Brush-Off Blast Cleaning

When viewed without magnification, the surface shall be free of all visible oil, grease, dirt, dust, loose mill scale, loose rust, and loose coating. Tightly adherent mill scale, rust, and coating may remain on the surface. Mill scale, rust, and coating are considered tightly adherent if they cannot be removed by lifting with a dull putty knife.

### SSPC-SP13 / NACE 6 Surface Preparation of Concrete

Provides requirements for surface preparation of concrete by mechanical, chemical, or thermal methods prior to the application of bonded protective coating or lining systems.

### **Surface Application Recommendations:**

**Previously Painted Surfaces:** Clean surface of all loose, peeling paint and foreign material; spot prime bare metal areas. If the paint is old, peeling or badly weathered, hand tool clean (SSPC-SP2) or power tool clean (SSPC-SP3). Glossy or Smooth surfaces should be sanded. If poor adhesion of existing coatings is noted or coating is loosed by blistering, rupture or scratching, aditional abrasion or removal methods may be necessary to provide a clean and sound surface.

**New Iron and Steel Metals:** Clean surface of all loose rust, grease, oil, and foreign material; spot prime bare metal. If the paint is old, peeling or badly weathered, hand tool clean (SSPC-SP2) or power tool clean (SSPC-SP3).

**New Galvanized Metal:** Allow to weather a minimum of six months prior to coating. Solvent clean as per SSPS-SP1 standard, then prime as required. When weathering is not possible, solvent clean as per SSPS-SP1 and apply a test patch, prime as required. Allow primer to dry one week before testing for adhesion. If adhesion is poor, brush blast is recommended to remove this treatment. Remove silicate or white rust by sanding (SSPC-SP7). Water-soluble contaminants should be rinsed off with water.

**New Aluminum:** New surfaces must be free of oils and lubricants often used in the fabrication or machining of aluminum. Use solvent cleaning preparation SSPC-SP1 with Lanco® Lacquer Thinner LT-102 to clean and remove any foreign matter that could affect the performance of the coating. This can also be accomplished on exterior products by weathering for a month to six weeks prior to the application of primer. Surface must be clean and free of contaminants. If detergent is used, be sure to rinse well, and allow to dry before paint. If small thin oxide film is found on surface, remove by hand cleaning SSPC-SP2 or power cleaning SSPC-SP3.

Masonry and Concrete Surfaces: New mortar plaster, stucco and concrete block must be cured prior to application. Remove any surface contaminant, form release, curing agents or efflorescence, surface must have a safe pH level under 9 prior to the application of paint or primer. Surface preparation of concrete by mechanical, chemical, or thermal methods as of SSPC-SP13 prior to the application of bonded protective coating or lining systems may be necessary. Prime with Lanco® Maxima HP Primer MA-3305 or Lanco® Stain Killer Primer WP-039.

**Wood and Plywood:** Sand rough areas and prime properly prepared surface with Lanco<sup>®</sup> Stain Killer<sup>™</sup> Primer WP-039. Maximum acceptable moisture content prior to coating new wood should be under 16%.

## **Method of Application:**

Stir thoroughly before using. Do not apply when surface or air temperature is below 50 °F or if rain is expected within 5 hours. Apply product with brush, roller or sprayer. Apply generously with a full brush or roller and avoid excessive brushing or spreading too thinly. Typical standard practice recommends intermixing when working with more than one container of the same color, to ensure color consistency.

**Mixing and Thinning:** Mix always thoroughly before application. Thinning is not recommended, if necessary use only 8oz. of Lanco<sup>®</sup> Mineral Spirits MS-107 per gallon.

**Brush:** Use a 3/8" solvent resistant PA-1982 or polyester brush PA-1999. **Roller:** Use a Lanco<sup>®</sup> All-Purpose 1/4" or 3/8" Enamel Roller PA-565 or PA-566. Apply generously, but avoid excessive brushing or reworking of painted areas, do not apply or spreading too thinly.

**Conventional Spray:** For suction feed, use a DeVilbiss MBC gun with an "E" tip and needle and 30 air cap or equivalent, at 40-45 psi atomizing pressure. For pressure feed, use a DeVilbiss MBC gun with an "E" tip and needle and 704 air cap or equivalent at 40-45 psi and 5-8 fluid pressure, 3/8" ID material hose, double-regulated pressure tank with oil and moisture separator. Apply two coats with overnight drying between coats to minimize pinholes on the surface is recommended. See equipment's manufacturer recommendation. **Airless Spray:** Minimum of 28:1 ratio pump, with a 0.013"-0.015" tip, 1/4" ID Teflon material hose. Apply two coats with overnight drying between coats to minimize pinholes on the surface is recommended. See equipment's manufacturer recommendation.

**Precaution:** Do not apply when air or surface temperature is below 50  $^{\circ}$ F (10  $^{\circ}$ C). Apply liberally,but do not overspread. Stop painting at least two hours before you expect dew to form or the temperature to fall below 50  $^{\circ}$ F (10  $^{\circ}$ C).

**Important:** It is important that you apply one coat of primer and two full coats of paint to achieve the warranty protection.

**Limited warranty:** The manufacturers liability in connection with the sale of this product extend only to the replacement price if it should fail to comply with quality standards or specifications.

Safety precautions: Refer to SDS sheet before use.

**Warning!:** If you scrape, sand, or remove old paint, you may release lead dust. Lead is toxic. Wear a NIOSH-approved respirator to control lead exposure. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead. For chemical emergency call ChemTrec



- NORTH AMERICA 600 Mid Florida Drive Airport Industrial Park of Orlando, Florida 32824 Tel. (407) 240-4000 Fax (407) 240-4046
- CARIBBEAN & SOUTH AMERICA Urb. Aponte #5, San Lorenzo, Puerto Rico USA 00754 Tel. (787) 736-4221 Fax (787) 736-5313
- CENTRAL AMERICA Zona Industrial Bes, lote #4, El Coyol de Alajuela, Costa Rica Tel. (506) 2438-2257 Fax (506) 2438-2162