

# CROMKOTE CODE: CK032

#### HIGH SOLIDS - HIGH GLOSS ACRYLIC FLOOR FINISH

DESCRIPTION:

CROSSCO – CROMKOTE (3th Step) is a fast dry, ultra durable floor finish with exceptional buffability. Tests on high traffic floor produce wear levels dramatically superior to conventional floor polishes on the market today. This product requires minimum maintenance, resists scuff marks thus reducing labor costs.

RECOMMENDED

USES:

CROSSCO – CROMKOTE is the premium *Low Maintenance* floor finish that provides the gloss and durability. Excellent for use on Vinyl, Vinyl Composition,

Asphalt, Rubber, Concrete, Flagstone, Brick, Terrazzo, Sealed Wood floors.

Designed for low maintenance floor care programs.

ADVANTAGES:

Super High gloss finish

•Could be used without sealer

Detergent resistant

•For high traffic areas

Self leveling

Easy to apply

## **PRODUCT CHARACTERISTICS**

Buffabiliyu .....Spray Buff or Restorer

Solids 25.0 ± 0.5%	Dry/Recoat time40 min
ColorMilky White	DetergencyExcellent
OdorMild	Waterspot ResistanceExcellent
pH8.0 – 9.0	VOC0.35 lbs/gal
ViscosityWater thin	Coverage3000 s.f./gal +/-
Gloss90+ specular	Storage/Stability2 years
LevelingExcellent	Weight per Gallon9.15 lbs./gal.

Freeze / Thaw Stability .. Keep from freezing



## **CROMKOTE**

F	FOR USE	SAFETY INFORMATION
- Vinyl Tile - Asphalt Tile - Rubber Tile - Flagstone - Ceramic Tile	- Vinyl Asbestos - Linoleum - Concrete - Terrazzo	Avoid contact with eyes, skin and clothing. Wear protective eyewear, gloves and footwear when handling. Avoid breathing of vapors. Keep out of reach of children. For use by trained personnel only. Keep unauthorized personnel away when applying to floor. Keep container closed during storage. For institutional and industrial use only.
		institutional and industrial use only.

GENERAL PRODUCT INFORMATION

#### DIRECTIONS

PREPARATION: If stripping is necessary, use CROSSCO WAXEX stripper and follow directions accordingly. Once floor is stripped, apply a coat of CROSSCO D.P. SEAL SEALER, let dry and apply desired finish coat.

If floor is in good condition and stripping is not necessary, sweep up excess dirt and dust and then clean with a good quality cleaner to remove dirt and oils. Follow with a thorough rinsing and allow to dry completely.

FINISHING: Spread a liberal coat of finish evenly across the floor with a clean mop or applicator. Allow each coat to dry at least 40 minutes before applying the next coat. Two or three coats are desired initially, depending on the condition of the floor and gloss desired.

*MAINTENANCE:* The floor may be maintained using a quality floor cleaner and damp mopping regularly. Spray buffing or mop-on restoring may also be done after sweeping up loose dirt and dust. Follow directions for each product accordingly.

Refer to product Material Safety Data Sheet (MSDS) prior to product use.

For chemical emergency only, call Chemtrec 1- 800-424-9300

<u>Notice</u>: The technical data contained herein are true and accurate to the best of our knowledge. Published instructions are subject to change without prior notice.

### AVAILABLILITY

CKU32-1	55 GAL
CK032-2	5 GAL
CK032-4	4/ 1 GAL
CK032-5	12/ 32oz Bottle